

# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

Run Summary							
Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?	
D1028-167	Dye	4/27/2009	ADS/TM	S11GG_030MH	Dry	NA	
Address	3001 Presbury Street		Location	Curb	Status	Public	Source Catch Basin



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary


Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?
D1028-167	Dye	4/27/2009	ADS/TM	S11GG_030MH	Dry	NA
<b>Address</b> 3001 Presbury Street			<b>Location</b> Curb	<b>Status</b> Public	<b>Source</b> Catch Basin	

### Observations & Photos

**Obs\_ID** D1028-167-OB01

**Nearest MH** S11GG\_030MH

**Comments** Dye observed 13.1 ft. downstream of S11GG\_030MH. Infiltration runner at joint from 5 to 7 oclock.



**Picture** \D1028-167-OB01-P01.jpg


**Comments** 13.1 ft. downstream of S11GG\_030MH along S11GG\_030G1.

---

**Obs\_ID** D1028-167-OB02

**Nearest MH** S11GG\_030MH

**Comments** Dye observed 16.5 ft. downstream of S11GG\_030MH. Infiltration runner at joint at 5 oclock.



**Picture** \D1028-167-OB02-P01.jpg

**Comments** 16.5 ft. downstream of S11GG\_030MH along S11GG\_030G1.

---

---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Nearest MH	Ground Condition	Notification Made?
D1028-167	Dye	4/27/2009	ADS/TM	S11GG_030MH	Dry	NA

<b>Address</b>	3001 Presbury Street	<b>Location</b>	Curb	<b>Status</b>	Public	<b>Source</b>	Catch Basin
----------------	----------------------	-----------------	------	---------------	--------	---------------	-------------

**Obs\_ID** D1028-167-OB03

**Nearest MH** S11GG\_030MH

**Comments** Dye observed 25.7 ft. downstream of S11GG\_030MH. Infiltration runner at joint at 5 o'clock.



**Picture** \D1028-167-OB03-P01.jpg

**Comments** 25.7 ft. downstream of S11GG\_030MH along S11GG\_030G1.